

FIG. 1







FIG. 2




One step heat treatment




Heat treatment temperature:1050°C




Heat treatment temperature:1100°C



Heat treatment temperature:1150°C




Heat treatment temperature:1200°C




Heat treatment temperature:1250°C

FIG. 3


Two steps heat treatment



Heat treatment temperature:
1050°C + 1100°C



Heat treatment temperature:
1050°C + 1150°C



Heat treatment temperature:
1050°C + 1250°C